

Oil Field Environmental Incident Summary

Incident: 20150102073640 **Date/Time of Notice:** 01/02/2015 07:36

Responsible Party: QEP ENERGY COMPANY

Well Operator: QEP ENERGY COMPANY

Well Name: P. LEVANG 1-14TH

Field Name: GRAIL

Well File #: 29749

Date Incident: 12/22/2014 **Time Incident:** 21:00

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 95

Sec: 11

Qtr: SE SE

Location Description:

Submitted By: Jerry Reinisch

Received By:

Contact Person: Jerry Reinisch
1050 17TH ST STE 500
DENVER, CO 80265

General Land Use: Pasture

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.5 Mile

Distance Nearest Water Well: 0.6 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	150	Barrels	150	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

clean brine water-low risk

Areal Extent:

Potential Environmental Impacts:

majority of the release was contained within containment area around the tank farm, remainder was contained on the lined and bermed drilling pad location. (40 X50 foot area)

Action Taken or Planned:

remaining fluid and fluid outside the tank farm containment vacuumed up off the liner and pumped with diaphragm pumps into alternate trucks, then placed back into the holding tank. These tanks should not be unattended while moving or rolling mud. Procedures will be modified to insure proper observation during this process.

Wastes Disposal Location: Recovered materials were vacuumed into trucks and placed back into the holding tank after the valve was repaired.

Agencies Involved:**Updates**

Date: 1/2/2015 **Status:** Reviewed - Assigned to Other Agency **Author:** Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location within a bermed site. NDIC retains oversight.